

$$EIy'''' = \frac{C}{(ax^2 - y)^2}$$

C and a are constant

$$y'''(200) = 0$$

$$y''(200) = 0$$

$$y'(0) = 0$$

$$y(0) = 0$$